

## NICOMATIC HEADQUARTERS

173, rue des Fougères / ZI Les Bracots  
74890 Bons-en-Chablais FRANCE  
Tel: (33) 4 50 36 13 85 Fax: (33) 4 50 36 11 33  
email: [nicomatic@nicomatic.fr](mailto:nicomatic@nicomatic.fr)

# CMM Catalogue Erratum v4.1

N°	PROBLEM / PRINTING MISTAKE OR ERROR / NEW INFO	N° PAGE	SOLUTION TO SOLVE THE PROBLEM IN THE NEXT PRINT
1	"D" sign inside the part numbering at the bottom of the page is not printed on several pages for CMM220 connectors	36-37 39-40	Correct in the next edition
2	In the chart at the bottom page we indicate tool HM800 and Positioner K778. Both need to be replaced by MH800 and Positioner K1692.	110	Correct in the next edition
3	The "W" code that has been added on page 45 for additional washers have been forgotten on pages 71 & 73.	71-73	Add in next edition
4	The typical markets for CMM micro-connectors that are defence, aerospace, railway, naval, medical & energy are not visible in the catalogue. Page 6 that cites the same level of information as on page 2 should be reviewed. Also the mention "up to 2 500 cycles" is false as the correct information is up to 5 000 cycles as stated on page 5.	6	Add market information & pictures that are representative and shown online
5	We do not show the 2D drawings for the female CMM100/200 connectors and state that the 90° SMT connector is available upon request. This has to be modified as the connector is available in standard.	25	Modify with the correct drawings
6	The connector P/N marking on CMM220, 320, 340 has been modified for the connector series and is no longer showing the gender, number of contacts & type of pin. The NCM mark & date code have been modified as well.	12-13	Change in the next issue of the catalogue
7	The 3D images of CMM connectors on these pages always show strain relief straps mounted on the housings. However, strain relief straps are supplied with all male CMM100/200 mounted with latches (L or FL) except for Y and YL terminations.	20-21	Clarify this by a note on page bottom in the next edition.
8	Special contacts for card edge connectors (30-1500-12) on pages 79 (for CMM220 series) and 80 (for CMM320 series) are not enough visible inside the catalogue.	79-80	Mention in the index page 123 under the chapters CMM220 & CMM 320.
9	The PCB layout for male 90° SMT contacts for CMM320 series P/N 30-1500-12 shows a wrong title for the PCB layout. It should be 30-1500-12 and not 30-1500-CMM.	80	Replace
10	Cable instructions are correct but need to be updated through new information that will be available for the next print.	114-115	Update
11	The sentence: " the strain relief straps are supplied with all male CMM 100/200 ..." can be confusing as these accessories are not supplied with all connectors.	22	Update by indicating to which connectors the strain relief straps apply.
12	The value on the drawings is wrong. nnn = 020 and 026 : pin number 1 on the 3Ds is on the right and not on the left.	53 & 61	Modify
13	The 2 <sup>nd</sup> & 4 <sup>th</sup> drawings from top of the page indicate a value of 10,65 mm max. The true value is 10,625.	48	Correct in next edition
14	The connectors shown on page 125 should be updated with new pictures and the texts can be reviewed with new information available for the next print. A QR code can be added to implement the online access.	125	Update

**Other mistakes are possible. Do not hesitate to let us know  
under [marketing@nicomatic.fr](mailto:marketing@nicomatic.fr).**